Morrow Yu, Deborah

From: Jaramillo, Ilyanna on behalf of FM - Work Service Center

Sent: Tuesday, September 23, 2014 8:32 AM

To: FM - Work Service Center

Subject: FM Notification to Perform Repairs on the Fire Sprinkler System at the Literature

Building

FACILITIES MANAGEMENT NOTIFICATION

September 23, 2014

Subject: FM Notification to Perform Repairs on the Fire Sprinkler System at the Literature Building

Start: Thursday, October 2, 2014, at Noon
End: Friday, October 3, 2014, at 4:00 pm

• System(s) to be Shut Down: Building Fire Sprinkler system

- **Purpose of Shutdown/Notification:** To perform repairs to the building sprinkler systems throughout campus to ensure compliance with our Title 19 requirements.
- **How Building Occupants will be affected** An FM contractor will be repairing and replacing sprinkler piping and/or sprinkler heads at the following locations:

<u>1st Floor</u> :	2 nd Floor continued
In elevator lobby	In hallway outside of room 238
West side of admin office lobby	In hallway outside of room 254
Center of admin office lobby	Control valve supervisory alarm does not send a signal with normal valve operation; Needs to be adjusted
In hallway outside of room 123	3 rd Floor:
In hallway outside of room 121	
Underneath stairs in stairway 1	3rd floor elevator lobby.
In hallway between men's and women's restrooms	In hall outside the men's restroom.
In hallway outside of room 155	In the hallway entrance between the women's and men's restroom.
In hallway outside of room 138	In the hallway outside room 355
In hallway outside of room 142	In the hallway outside between rooms 335 & 337
In hallway outside of room 149	In the hallway outside room 338
2 nd Floor:	In the hallway outside room 354
	In the hallway outside room 340
In elevator lobby	In the hallway outside room 342
In hallway outside of room 216	In the hallway outside room 348
In hallway outside of room 234	In the hallway outside room 346
In hallway outside of room 221	Control valve supervisory alarm does not send a signal with normal valve operation; Needs to be adjusted
In hallway outside of stair 1 entrance	4 th Floor:
Above riser in stair 1	
In hallway between women's and men's restrooms	In the hallway outside room 454
West head in women's restroom	In the women's restroom
East head in women's restroom	In the hallway outside the elevator lobby double doors
In hallway outside of room 255	In the elevator lobby
In hallway outside of room 237	Control valve supervisory alarm does not send a signal with normal valve operation; Needs to be adjusted

• **Special Instructions:** During the repairs, the contractors will be at the locations listed above. They will cover up any equipment and/or furniture in office areas and labs. If there are any critical areas that FM should be aware of or if you have concerns, please contact Jose Moret at jmoret@ucsd.edu as soon as possible to request a schedule change or special preparation.

Should you have any questions or concerns, please contact the Facilities Management Customer Relations Help Desk at x42930.

Gina Majorossy
University of California, San Diego
Facilities Management
Customer Relations
Phone: (858)534-2930

Web: http://fm.ucsd.edu